


US EPA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill		03/30/2012	1627		
4. Unit Name/Designators		5. Unit Leader		6. Operational Period :	
Operations Unit/SORT		Name:	Dan Capone & Joe Victory (START/US EPA)	From:	03/30/2012 0700
		Position:	Operations Section Chief	To:	03/30/2012 1700
7. Personnel Roster Assigned					
Name		ICS Position		DUTY CELL	
Dan Capone		Operations Section Chief			
Joe Victory		Operations Section Chief			
Rex Johnson		Director			
Dan Zahner		Field Team Lead			
Brian Ross		SORT Team #2			
8. Activity Log					
Activity Area	Division D, various locations			LAT	LAT
				Various	Various
				(DD.MMMM)	(DD.MMMM)
<u>OIL OBSERVED</u>	<u>EXTENT OF OIL IMPACTED AREA</u>				
	<u>DENSITY OF OIL /SHEEN</u>				
Total Collection Points					
Total Boom Deployed					
Activity	<p><u>Weston/START Shoreline and Overbank Reassessment Technique (SORT) Team Activity:</u> Provided START oversight for Enbridge Team 5 as WESTON SORT Team 2 at the following locations:</p> <ul style="list-style-type: none"> • 21.00 RDB 2 team determined no oil sheen, patties, coating, or stains observed • 0951 team heard thunder and returned to the D2 boat launch to wait out the storm • 1157 team returned to SORT work • 21.00 RDB 1 team determined no oil sheen, patties, coating, or stains at accessible portions of the polygon and created a new polygon (21.00 RDB 151) for the portion required reassessment due to water depth greater than 2' • 21.25 LDB 2 this polygon will require reassessment, it is within the river and greater than 2' deep • 21.50 RDB 500 this polygon will require reassessment, it is an oxbow and we boated through the entire polygon • 21.50 RDB 4 team determined no oil sheen, patties, coating, or stains observed • 22.00 RDB 12 team determined no oil sheen, patties, coating, or stains observed • 22.25 I 500 team determined no oil sheen, patties, coating, or stains observed within majority of the polygon and recorded a new polygon (22.25 I 100) for an area of trace sheen 				

Health and Safety Issues	Proper safety guidelines were followed during the thunderstorm threat. All team members sought shelter in their vehicles at the boat launch as soon as possible following the first clap of thunder and until one half hour after the last.
Comments	Team worked well together and reached agreement before departing all polygons. Work was done safely and efficiently.